




Solar MC4 Crimping Tool



Model : LY-2546B

Range : 2.5–6.0mm² 14-10AWG

Weight : 0.6Kg





Capacity: 2.5/4/6mm² (14-10AWG)

MC4 Connectors



Precision Dies



Integral Lock



TPR+PP Handle Material



First Step Stripping



Use the stripping tool to strip the cable.



Strip the cable about 7mm length.



Cable stripping steps finished.

Second S. Crimping



Put the metal pin to crimping tool tooth, and crimp lightly.



Put the stripped cable into the pin, crimp it tightly until it loosens.



Pin crimping steps finished. Same as the other one.

Third Step Inserting



Put the crimped male pin into male housing tightly until it's set by "Click".



Put the crimped female pin into female housing tightly until it's set by "Click".



Use spanner to tighten the screw on both sides.

Fourth Step Connecting



Connect male and female.



Joint tightly until it's set by "Click".



Open and joint easily by hand.

